

POLISH CENTRE FOR TESTING AND CERTIFICATION

02-699 Warszawa, ul. Kłobucka 23A

Mechanical Laboratory

tel.: (+48 22) 46 45 594; fax: (+48 22) 46 45 563 e-mail: labmech@pcbc.gov.pl

Date 24.09.2009

TEST REPORT NO. BR - 151/L - 274/2009

Page 1 of 6

Subject of testing:

Toilet chair

Classification according to PN-EN ISO 9999:2001:

09 33 03

Type / Model:

KAKADU

Factory ref. no.: 8120840085

Manufacturer:

MOBILEX A/S, Noerskovvej I

Number of specimens: 1

Applicant:

BEO MedConsulting GmbH

DK - 8660 Skanderborg

Helmholtzstr. 2, D-10585 Berlin

Kind of testing

Testing scope according to application of Client

Mechanical testing for conformity with PN-EN 12183: 2002 cl. 7.1, 7.2.1, 7.2.2;

PN - ISO 7176 -3:1998: PN - ISO 7176 -8:2002

Test started: 16. 09.2009 r.

Test finished: 24.09.2009 r.

Performed by:

Checked by:

Approved by:

KIEROWNIK LABORATORIUM MECHANICZNEGO

Mirosław Szymański

Ireneusz Czerwiński

mgr inż. Andrzej Tkaczyk

Special comments / enclosures:

hunarelles

Annex 1: Identyfication of toilet chair elements

Copyright © 2005 by Polish Centre for Testing and Certification (applicable to report form) Test results refer only to tested units.

Test results reported here are not applicable to the further modifications of the product affecting his structure, material or technology. This test report shall be neither copied differently as in the whole nor be published without written consent of the Laboratory.





Report no.: BR - 151/L-274/2009

Page: 2 of 6

CHARACTERISTIC OF TOILET CHAIR KAKADU

Name of toilet chair: KAKADU Factory ref. no. 8120840085 Maximum load capacity: 130kg Overall mass of toilet chair: 12,9 kg Description Comments **Dimensions:** 915mm Length (footboard in maximum extension position): 967mm Height: Width: 547mm Aluminum allov **Construction of frame:** Material: Method of fastening frame elements: Welding Unfolding Folding/unfolding: Ø of wheel: 125mm Castor wheels 32mm Width: Plastic Material of ring of a wheel: Plastic Material of fork: NO Vertical adjustment (number of fixing positions) NO Horizontal adjustment (number of fixing positions): NO Adjustment of axis inclination angle: Folding/unfolding: Unfolding **Backrest** Backrest NO stepless: NO inclination number of fixing positions adjustment NO Tilt levers Two singular: NO One lateral: One transverse handle **Push handles** Kind: YES Parking brake Left: Number: 2 YES Number: 2 Right: Lever, foot-push brake, Kind: wheel-mounted Plastic Material of lever: Non-adjustable brake Fastening to frame: Upholstery Material: Soft Plastic Black Colour: Wheel space in forward direction position: 467mm Wheel space in backward direction position: 467mm NO Legrests Common for both legs: YES Separate for each leg: NO Stationary: YES Folding: YES Vertical adjustment (number of fixing positions) stepless NO Horizontal adjustment (number of fixing positions): NO Angle adjustment (number of fixing positions): Material of legrest: Aluminum alloy Plastic NO Accessories Seat belt YES Service:



Page: 3 of 6

PHOTO OF TOILET CHAIR







Report no.: BR - 151/L-274/2009

Page: 4 of 6

חח	TA	
0	1	T

NORMATIVE REFERENCES	Applied
PN-EN 12182:2002 Technical aids for disabled persons – General requirements and test methods	NO
PN-EN 12183:2002 Manually propelled wheelchairs – Requirements and test methods	YES
PN-EN 12184:2002 Electrically powered wheelchairs, scooters and their chargers – Requirements and test method	NO
ISO 7176-1:1999 Wheelchairs – Determination of static stability	NO
PN-ISO 7176-2:1998 Wheelchairs – Determination of dynamic stability of electric wheelchairs	NO
PN-ISO 7176-3:1998 Wheelchairs – Determination of efficiency of brakes	YES
ISO 7176-4:1997 Wheelchairs – Energy consumption of electric wheelchairs and scooters and determination of theoretical distance	NO
PN-ISO 7176-5:2001 Wheelchairs – Determination of overall dimensions, mass and turning space	NO
PN-ISO 7176-6:1998 Wheelchairs – Determination of maximum speed, acceleration and retardation of electric wheelchairs	NO
PN-ISO 7176-7:2001 Wheelchairs – Measurement of seating and wheel dimensions	NO
PN-ISO 7176-8:2002 Wheelchairs – Requirements and test methods for static, impact and fatigue strengths	YES
ISO 7176-9:2001 Wheelchairs – Climatic test for electric wheelchairs	NO
PN-ISO 7176-10:1998 Wheelchairs – Determination of obstacle-climbing ability of electric wheelchairs	NO
PN-ISO 7176-14:2001 Wheelchairs – Power and control systems for electric wheelchairs – Requirements and test methods	NO
PN-ISO 7176-15: 2002 Wheelchairs – Requirements for informative disclosure, documentation and labelling	NO
PN-ISO 7176-16:2001 equivalent: PN-90/P-04823 Wheelchairs. Resistance to ignition of upholstered parts – Requirements and test methods	NO
Note: Toilet chair with adjustment elements regulated in a factory was performed	

Note: Toilet chair with adjustment elements regulated in a factory was performed

TEST	RESULTS	according	to PN-EN	12183
	DESIGN	REQUIREN	MENTS	

Requireme nts according to clause	Test method according to clause	Checked characteristics/assemblies/parameters	Real value	Test result	Comments
6.1.1.	6.1.2	Legrests and footrests	? 	N/T	
6.2.	V/I	Pneumatic tyres		N/T	
6.3.	V/I	Fastening of seat belt		N/T	
6.4.	V/I	Side and back rests		N/T	
6.5.	V/I	Wheelchairs to be used as seats in motor vehicle		N/T	
6.6.	V/I	Brakes		N/T	
6.7.	V/I	Mass of components Mass of the biggest component:		N/T	
6.8.	V/I	Anti-tilting devices Backwards static stability:		N/T	
		FUNCTIONAL PROPERTIES	S		
7.1.	PN-ISO 7176-8	Static, fatigue and impact strength	Conf.	Pos.	
7.2.1.	7.2.3	Parking brake efficiency - force applied to hand brakes: - force applied to pushed in foot brake: - force applied to pulled foot brake: - effectiveness of braking wheelchair facing up to the	Conf. 90 N	Pos. N/A N/A	For foot-push brake, the engagement force below 100 N is required
	PN-ISO 7176-3 clause 7		Conf.	Pos.	
		slope: - effectiveness of braking wheelchair positioned sideward down the slope	Conf.	Pos.	No rotation or wheel spin when wheelchair is on inclined plane of 7° slope
		sideward down the slope effectiveness of braking wheelchair facing down the slope:	Conf.	Pos.	
7.2.2.	7.2.4	Fatigue strength of parking brake	Conf.	Pos.	60000 cycles



Mechan	nical Lab	oratoi	ry of	PCBC R	epor	t no.:	BF	R – 151	/L-274/2009 Page: 5 of 6
7.3	PN-ISO 7176-16	Resist	Resistance to ignition of upholstery parts				N/T	1	remont strong and an area of
7.5.1.	7.5.2	Push 1	force				N/T	,	-
7.6.1.	7.6.2			stics of tracks of wheelchair wheels			N/T		
8.2.	Ogl.	Service					N/T		
8.3.	Ogl.	Marki	ing			2	N/T		
				TEST RESULTS according to PN-ISO 7	7176-	-3			
Requirem ents according to clause	Test method according to clause	(Chec	eked characteristics/assemblies/parameters]	Real val	lue	Test result	Comments
PN-EN 12183 cl. 7.2.1	7.1 V/I Measur.	Effectiveness of parking brake of wheelchair positioned forwards down the slope		1	Conf 15° Wheelchd loses stabi	air	Pos.	No rotation or wheel spin when wheelchair is on inclined plane of	
PN-EN 12183 cl. 7.2.1	7.1 V/I Measur.	e		ectiveness of parking brake of wheelchair position kwards down the slope		Conf 15° Wheelchd loses stabl	air	Pos.	7° slope (requirements of PN-EN 12183 p. 7.2.1)
PN-EN 12183 cl. 7.2.1	PN-EN 12183 cl. 7.2.3 Measur.	ing b		asurement of force acting on brake lever		90N		Pos.	For foot-push brake, the engagement force below 100 N is required (requirements of PN- EN 12183 cl. 7.2.1)
7.2.1.a	V/I Measur.	υ on		king distance during drive with maximum speed forwa norizontal plane	ırds	-		N/A	Testing relates electrically powered wheelchairs
7.2.1.b	V/I Measur.			king distance during drive backwards on horizontal plan-	е	.=		N/A	Testing relates electrically powered wheelchairs
7.2.1.c	V/I Measur.	Servic	Braking distance of wheelchair during drive forwards on slope of 5°			-		N/A	Testing relates electrically powered wheelchairs
7.2.2.	V/I Measur.		Resistance of braking system to increased temperature caused by long braking during drive forwards on horizontal plane		ong	-		N/A	badanie dotyczy wóz- ków inwalidzkich na- pedzanych elektr.
7.2.3.a	V/I Measur.			Braking distance of wheelchair during drive w maximum speed forwards on horizontal slope	vith	_		N/A	Testing relates electrically powered wheelchairs
7.2.3.b	V/I Measur.		Braking distance of wheelchair during drive with maximum speed forwards on slope of 5°		vith	-		N/A	Testing relates electrically powered wheelchairs
				TEST RESULTS according to PN-ISO	7170	5-8			
Wyma- gania wg.pkt.	Metoda bad. wg.pkt		Checked characteristics/assemblies/parameters			Real va	alue	Test result	Comments
4.	8.4.			- resistance to forces acting downwards		Conj		Pos.	loading 988N
4.	8.5.		Footrests - resistance to forces acting upwards			Conj	f.	Pos.	loading 1300N
4.	8.6.		Anti-tip levers					N/A	
4.	8.7.		Grips					N/A	
4.	8.8.		Armrest – forces acting upwards					N/A	
4.	8.9.		Footrest – forces acting upwards		-		ſ	N/A	loading 2280N
4.	9.3.		Handle grips for pushing – load acting upwards Backrest – impact strength		-	Conj Conj		Pos. Pos.	25kg pendulum impact
4.	9.3.		Driving wheel – impact strength		_	Con		Pos.	10kg pendulum impact
4.	9.4.		Castor/front wheel – impact strength			Con		Pos.	10kg pendulum impact
4.	9.6.3.		Footrest – side impact		+	Con		Pos.	10kg pendulum impact
4.	9.6.4.	Footrest – in-line impact			Conf.		Pos.	10kg pendulum impact	
4.	9.7.2.		Frontal part of wheelchair – directly impact			Conf.		Pos.	10kg pendulum impact
4.	9.7.3.			part of wheelchair – displaced impact		Con		Pos.	10kg pendulum impact
4.	10.4.2		Testing of manually propelled wheelchair on two-drum machine			Con		Pos.	200 000 of cycles with full loading of wheelchair (130kg)
4.	10.4.3	. Me	easur	ement of initial current for electrically powered wheelch	air			N/A	



Mechani	cal Labora	ntory of PCBC Rep	ort no.: BR		2-274/2009 Page: 6 of 6
Requirement s according to clause	Test method according to clause	Checked characteristics/assemblies/parameters	Real value	Test result	Comments
4.	10.4.4.	Testing of electrically powered wheelchair on two-drum machine		N/A	
4.	10.5.	Drop testing		N/A	**)
		ent's demand, the test was performed on a testing stand non equippe	ed with obstacle	es.	
**) - Accor	rding to the c	lient's demand the drop test was not performed			

Pos. – positive; Neg – negative; N/T – not tested; N/A – not applicable; N/R – not required , N/O – not occurred , V/I.- visual inspection, Conf.- conformed.

Final asses	ssment
PN-EN 12182:2002	N/T
PN-EN 12183:2002	Pos.
PN-EN 12184:2002	N/A
ISO 7176-1:1999	N/T
PN-ISO 7176-2:1998	N/A
PN-ISO 7176-3:1998	Pos.
ISO 7176-4:1997	N/A
PN-ISO 7176-5:2001	N/T
PN-ISO 7176-6:1998	N/A
PN-ISO 7176-7:2001	N/T
PN-ISO 7176-8:2002	Pos.
ISO 7176-9:2001	N/A
PN-ISO 7176-10:1998	N/A
PN-ISO 7176-14:2001	N/A
PN-ISO 7176-15: 2002	N/T
PN-ISO 7176-16:2001	N/T

Note: Conformity assessment of product according to standard requirements refer to the scope of mechanical tests ordered by client

